



## PV

### Vibrating plate

The PV1 vibrating plate can work together with **the MC 2 and MC 4 capsule filling machines** to facilitate the descent of the powders inside the capsules.

PV Vibrating plate, is used to promote homogeneous filling of capsules in the presence of even low-flowing powders.

The vibrating plate has an operator-controlled vibration intensity adjustment system.

POWER CONSUMPTION kW	POWER SUPPLY V	DIMENSIONS LXWXH mm	WEIGHT kg
0,07	110/230 Single Phase	240x170x100	3